



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
December 19, 2006

Supervisor ADRH

Mine Name: Mayfield Quarry
Operator Name: Phyllis Bown

Permit number: M0390011
Inspection Date: November 15, 2006
Time: 4:00 pm

Inspector(s): Lynn Kunzler, DOGM
Other Participants: Jerome Bown
Mine Status: Site Reclaimed

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Operator had requested inspection of final reclamation work.

Inspection Summary:

9. Reclamation of this site has been completed. The operator was able to locate a topsoil borrow area and had spread a 1-2 inches of soil prior to seeding.

Conclusions and Recommendations:

The status of this file should be changed to reclaimed. Division should continue to visit this site when in the area to monitor revegetation establishment.

Inspector's Signature

LK:pb

O:\M039-Sanpete\S0390010-Ninemile\inspections\insp-11162006.doc

Date: December 19, 2006